

Stress Corrosion Cracking

Class Exercise



| Type | Susceptible Alloys | Conditions for Cracking | Fixes |
|--------------------------|--|---|--|
| Chloride | 300 Series Stainless Steels | A. Evaporative Heat Flux Which Produces Cl^- Deposits B. Usually Above 140-150°F (60-65°C) C. Low pH is Bad | A. Stress Relief B. Use Duplex or Ferritic Stainless Steels C. Use High Nickel (>30-40%) Alloys, Titanium, Copper Alloys |
| Polythionic | 300 Series Stainless Steels (Sensitized) | A. Shutdowns B. Water and Sulfide Scale | A. Use 321 SS or 347 SS B. Shutdown Precautions: (1) Soda Ash Wash and (2) N_2 Blanket |
| Caustic | 300 Series Stainless Steels and Carbon Steel | A. Hot Deposits | A. Stress Relief B. Use Monel or Other Nickel-Based Alloys C. Keep Generator Tubes Submerged |
| Ammonia | Brasses (Cu-Zn) | A. Ammonia + O_2 + H_2O | A. Remove O_2 and Use Acid Washes at Shutdown B. Use Alloys Without Zinc (e.g., CuNi) |
| Wet H_2S | Carbon Steel Vessels | A. H_2S Level >50 ppm and H_2O B. More Likely if Cyanides or Ammonia Present C. Mostly Vessels, Rarely Piping | A. Use Coating or Cladding B. Remove CN^- With Polysulfide |